HEWLETT® PACKARD

HP B3740A

Configuration Guide

HP 16500B Minimum Software Configuration	Version 2.0
HP 16500B Minimum Hardware Configuration	HP 16500L Interface Card (Ethernet LAN) HP 16550A or HP 16555A Logic Analyzer Card
Preprocessors	All HP and Third Party-supplied preprocessors that support the HP 16550A or HP 16555A module can be used with the HP B3740A.
Language Tool Connectivity	Any language system that generates HP/MRI IEEE695, Intel OMF286, or Intel OMF386 is supported directly by the HP B3740A; the HP B3740A can extract symbolic information automatically from these OMFs. If your language system generates a different file format, a generic ASCII format is supported. You simply create an ASCII file, which maps symbol names to addresses.
Source Language Supported	All source languages are supported; the B3740A simply displays the source file indicated in the OMF or in the user-specified source file search path.
PC Minimum Configuration	25 MHz 80386 with 8 M RAM 4 M free hard disk space Windows 3.1

PC Networking Packages Supported	HP-ARPA Novell-WP Windows for Workgroups with Microsoft-TCP/IP [WINSOCK 1.1] LAN Manager 2.1 with Microsoft-TCP/IP [WINSOCK 1.1] PC-NFS [WINSOCK 1.1] (version 5.0 with patch from SUN)
HP series 700 Minimum Configuration	HP-UX 9.0
Sun Sparc Minimum Configuration	SUN/OS 4.1.3 or SUN Solaris 2.3

HEWLETT® PACKARD

For more information, call your local HP sales office listed in your telephone directory, or an HP regional office listed below:

United States:
Microprocessor Hotline
(800) 447 3282

Hewlett-Packard Company
2101 Gaither Road
Rockville, MD 20850
(301) 258-2000

Hewlett-Packard Company
5201 Tollview Drive
Rolling Meadows, IL 60008
(708) 255 9800

Hewlett-Packard Company
1421 S. Manhattan Ave
Fullerton, CA 92631
(714) 999-6700

Hewlett-Packard Company
2000 South Park Place
Atlanta, GA 30339
(404) 955-1500

Canada:
Hewlett-Packard Ltd.
5150 Spectrum Way
Mississauga, Ontario L4W 5G1
(416) 206 4725

Europe:
Hewlett-Packard
European Marketing Centre
P.O. Box 999
1180 AZ Amstelveen
The Netherlands
31 20 547 9858

Japan:
Yokogawa-Hewlett-Packard Ltd.
Measurement Assistance Center
9-1, Takakura-Cho, Hachiojo-Shi,
Tokyo 192, Japan
(81) 426 48 0722

Latin America:
Hewlett-Packard
Latin American Region Headquarters
5200 Blue Lagoon Drive, 9th Floor
Miami, Florida 33126, U.S.A.
(305) 267 4245/4220

Australia/New Zealand:
Hewlett-Packard Australia Ltd.
31-41 Joseph Street
Blackburn, Victoria 3130
Australia
Melbourne Caller 272 2555
(008) 13 1347

Far East:
Hewlett-Packard Pacific Ltd.
17-21/F Shell Tower, Time Square,
1 Matherson Street, Causeway Bay,
Hong Kong
(852) 599 7978

Technical information in this document is subject to change without notice.

Printed in U.S.A. 6\94
5962-9887 E